

SUBJECT: VL2500™ Luminaire Software Update	SERIES: 2000
DISTRIBUTION: Service Centers, End Users	STATUS: Routine

Introduction

Embedded Software Update

Software update **06/27/08** for **VL2500™** **Luminaires** is now available. This technical bulletin covers all changes in this new version.

For instructions on downloading and installing VARI***LITE**[®] luminaire software, refer to technical bulletin LSW-002.

If you have any questions regarding this release or your VARI***LITE**[®] product, please contact Vari-Lite Customer Service at 1-877-VARILITE (or +1-214-647-7880) or via e-mail at customerservice@genlytecontrols.com.

Release Notes

Improvements in New Version

VL2500™ **Luminaires:**

- Improved display performance.
- Bug fix: When running the "Fixed Gobo Sensor" test, the VL2500 no longer displays an error message when the test passes.

CAUTION: Please note that operating arc lamps in standby mode for extended periods of time, or short burning (less than 5 minutes) after switch-on, can cause wall blackening. This may cause a reduction in lamp life and/or performance.

VARI***LITE**[®], VL500™, VL1000™, VL2000™, VL2500™, VL3000™, and VL3500™ are trademarks of Philips Group.

28-JULY-2008

BULLETIN NO. **LSW-041**