PHILIPS

VARI✳LITE TECHNICAL BULLETIN

SUBJECT: **VL1100 ERS Luminaire Software Release**	SERIES: **VL1100**
DISTRIBUTION: **Service Centers, End Users**	STATUS: **Routine**

Introduction

Embedded Software Release

Vari-Lite has a new software release for VL1100 ERS Luminaires. Software version **11/14/11** (file name, **VL1100_111411.bin**) is now available for download and installation. Vari-Lite recommends all owners and users of the VL1100 ERS Luminaire download and install this new version of software from the Support section of the Vari-Lite web site (www.vari-lite.com). Please review this bulletin in its entirety before downloading and installing the software.

VL1100 ERS Luminaires manufactured on and after **12/12/11** will have this software installed.

⚠ **Note: This software update is for VL1100 ERS Luminaires only. Software for VL1100 ERS Luminaires should not be installed or used in VL1000 ERS Luminaires.**

For instructions on downloading and installing VARI✳LITE luminaire software, refer to luminaire's user manual.

For more information on the USB Luminaire Programming Kit (Vari-Lite part number 28.8500.0054), please contact your Authorized VARI✳LITE Dealer or Vari-Lite customer service.

If you have any questions regarding this release or your VARI✳LITE product, please contact Vari-Lite Customer Service at 1-877-VARILITE (or +1-214-647-7880) or via e-mail at entertainment.service@philips.com.

Release Notes

Updates to VL1100 ERS Luminaire software (11/14/11):

- Removes an UNUSED test feature in the test menu section that can lead to a false error (Pan Sensor Error).

- This fixture does not use a pan sensor. There are no modifications to make to existing fixtures to use this software. It is recommended this software be downloaded and installed.