

SUBJECT: VL2500™ Luminaires Software Update	SERIES: 2000
DISTRIBUTION: Service Centers, End Users	STATUS: Routine

Introduction

Embedded Software Update

This software update, dated **09/13/05**, is for the **VL2500™ Luminaires** only. This technical bulletin covers all changes in this new version of software.

For instructions on downloading and installing VARI*LITE® luminaire software, refer to technical bulletin LSW-002.

If you have any questions regarding this release or your VARI*LITE® product, please contact Vari-Lite Customer Service at 1-877-VARILITE (or +1-214-647-7880) or via e-mail at customerservice@genlyte.com.

Release Notes

Improvements in New Version

Improvements made to the VL2500™ Luminaires (09/13/05) software:

- Operation - Code was moved within the software file to eliminate the risk of the luminaire inadvertently dousing and resetting during operation of certain cues.
- Magenta Wheel Reset - The magenta color wheel will now correct itself by simply taking the magenta value to 0% and then closing the dimmer wheel.