

VARI***LITE** TECHNICAL BULLETIN

SUBJECT: VL3515 Spot Luminaire Software Release	SERIES: 3000
DISTRIBUTION: Service Centers, End Users	STATUS: Routine

Introduction

Embedded Software Release

Vari-Lite has a new software release for VL3515 Spot Luminaires. Software version **08/28/12** (file name, **VL3515_082812.bin**) is now available for download and installation. Vari-Lite recommends all owners and users of the VL3515 Spot Luminaires download and install this new version of software from the Support section of the Vari-Lite web site (www.vari-lite.com). Please review this bulletin in its entirety before downloading and installing the software.

Note: VL3515 Spot Luminaires manufactured on and after **08/26/12** will have this software installed. This software may be loaded in all previously manufactured fixtures.

IMPORTANT! An updated software version is available for VL3015 Spot Luminaires. For the software for VL3015 Spot Luminaires, refer to technical bulletin LSW-071.

For instructions on downloading and installing VARI***LITE** luminaire software, refer to luminaire's user manual.

For more information on the USB Luminaire Programming Kit (Vari-Lite part number 28.8500.0054), please contact your Authorized VARI***LITE** Dealer or Vari-Lite customer service.

If you have any questions regarding this release or your VARI***LITE** product, please contact Vari-Lite Customer Service at 1-877-VARILITE (or +1-214-647-7880) or via e-mail at entertainment.service@philips.com.

Release Notes

Updates to VL3515 Spot Luminaire software (08/28/12):

- Addresses and fixes a reported issue where the fixture may, inadvertently, lock up when an individual reset command is activated /sent to the fixture through the control channel.