

## VARI\*LITE TECHNICAL BULLETIN

SUBJECT: <b>VL3015 Spot Luminaire Software Release</b>	SERIES: <b>3000</b>
DISTRIBUTION: <b>Service Centers, End Users</b>	STATUS: <b>Routine</b>

## Introduction

---

### Embedded Software Release

Vari-Lite has a new software release for VL3015 Spot Luminaires. Software version **08/28/12** (file name, **VL3015\_082812.bin**) is now available for download and installation. Vari-Lite recommends all owners and users of the VL3015 Spot Luminaires download and install this new version of software from the Support section of the Vari-Lite web site ([www.vari-lite.com](http://www.vari-lite.com)). Please review this bulletin in its entirety before downloading and installing the software.

---


**Note:** VL3015 Spot Luminaires manufactured on and after **08/26/12** will have this software installed. This software may be loaded in all previously manufactured fixtures.


---


---

**IMPORTANT!** An updated software version is available for VL3515 Spot Luminaires. For the software for VL3515 Spot Luminaires, refer to technical bulletin LSW-072.

---

For instructions on downloading and installing VARI\*LITE luminaire software, refer to luminaire's user manual.

For more information on the USB Luminaire Programming Kit (Vari-Lite part number 28.8500.0054), please contact your Authorized VARI\*LITE Dealer or Vari-Lite customer service.

If you have any questions regarding this release or your VARI\*LITE product, please contact Vari-Lite Customer Service at 1-877-VARILITE (or +1-214-647-7880) or via e-mail at [entertainment.service@philips.com](mailto:entertainment.service@philips.com).

## Release Notes

---

### Updates to VL3015 Spot Luminaire software (08/28/12):

- Addresses and fixes a reported issue where the fixture may, inadvertently, lock up when an individual reset command is activated /sent to the fixture through the control channel.