

VARI*LITE TECHNICAL BULLETIN


SUBJECT: VL440 / VL770 / VL880 Spot Luminaire Software Release	SERIES: 400/700/800
DISTRIBUTION: Service Centers, End Users	STATUS: Routine

Introduction


Embedded Software Release

Vari-Lite has a new software release for VL440 / VL770 / VL880 Spot Luminaires. Software version **10/23/13** (file name, **SVL_102313.bin**) is now available for download and installation. Vari-Lite suggests all owners and users of the VL440 / VL770 / VL880 Spot Luminaires download and install this new version of software from the Support section of the Vari-Lite web site (www.vari-lite.com). Please review this bulletin in its entirety before downloading and installing the software.

Note: VL440 / VL770 / VL880 Spot Luminaires manufactured on and after **11/12/13** will have this software installed. This software may be loaded in all previously manufactured fixtures.

For instructions on downloading and installing VARI*LITE luminaire software, refer to luminaire's user manual.

For more information on the USB Luminaire Programming Kit (Vari-Lite part number 28.8500.0054), please contact your Authorized VARI*LITE Dealer or Vari-Lite customer service.

If you have any questions regarding this release or your VARI*LITE product, please contact Vari-Lite Customer Service at 1-877-VARILITE (or +1-214-647-7880) or via e-mail at entertainment.service@philips.com.

Release Notes

Updates to VL440 / VL770 / VL880 Spot Luminaire Software (10/23/13):



Update Summary

- Improved operation and addresses field reported bugs in the following mechanisms and / or fixture operation:
 - a. Zoom mechanism edge tracking improved to address erroneous error messages.
 - b. LCD Display on / off operation.
 - c. Prism rotation (to prevent intermittent stalling of prism motor).
 - d. Improved dimmer operation (dimmer wheel travel - shortest path instituted).

VARI*LITE TECHNICAL BULLETIN

- e. CYMD wheel travel improved.
- f. Improved cooling operation (VL440 spot luminaires only).
- g. Addressed and corrected erroneous error messages from tilt encoder.
- h. Addressed and corrected general fixture reset and recalibration issues that were reported.
- Incorporates all software improvements from all previous versions.

CONTACT INFORMATION

For more information on this technical notice or on VARI*LITE products, please contact your Authorized VARI*LITE Dealer or Vari-Lite customer service.