

SUBJECT: VL4000 BeamWash Luminaire Software Release	SERIES: 4000
DISTRIBUTION: Dealers, Service Centers, End Users	STATUS: Routine

Introduction

Embedded Software Release

Vari-Lite has a new software release for VL4000 BeamWash Luminaires. Software version **02/22/16** (file name, **VL4000BW_022216.bin**) is now available for download and installation.

Vari-Lite suggests all owners and users of the VL4000 BeamWash Luminaires download and install this new version of software from the Support section of the Vari-Lite web site (www.vari-lite.com).

Please review this bulletin in its entirety before downloading and installing the software.


Note: VL4000 BeamWash Luminaires manufactured on and after **04/06/16** will have this software installed. This software may be loaded in all previously manufactured fixtures.




Important Notes About this Version of Software



- * *Please review this bulletin in its entirety before downloading and installing the software.*
- * *Power recycling is required after new software is installed.*


About PEGASUS Upload Software

For instructions on downloading and installing VARI*LITE luminaire software, refer to luminaire's user manual.

The PEGASUS Upload Software and luminaire firmware files are available for download, at no charge, from the Philips Vari-Lite web site at www.vari-lite.com in any luminaire product downloads support section.

For more information on PEGASUS Upload Software, please refer to Vari-Lite Technical Notice TN-349 (located in any product downloads Support section on the Vari-Lite web site) or contact your Authorized VARI*LITE Dealer or Vari-Lite customer service.

Note: For users that wish to purchase a Philips VARI*LITE USB Upload Cable, contact Authorized Philips VARI*LITE Dealer and order part number: **PEGASUS**.

If you have any questions regarding this release or your VARI*LITE product, please contact Vari-Lite Customer Service at 1-877-VARILITE (or +1-214-647-7880) or via e-mail at entertainment.service@philips.com.

VARI*LITE

TECHNICAL BULLETIN

Release Notes

Updates to VL4000 BeamWash Luminaire Software (02/22/16):

- Improved internal checks to prevent false lamp-off errors and other false errors.
- Improved pan and tilt encoder and motor relationship when moving to holding power.
- RDM UID will no longer display 0:0:0:0:0 in the log file when operating off battery.