

SUBJECT: VL4000 Spot Luminaire Software Release	SERIES: 4000
DISTRIBUTION: Service Centers, End Users	STATUS: Routine

Introduction

Embedded Software Release

Vari-Lite has a new software release for VL4000 Spot Luminaires. Software version **01/26/15** (file name, **VL4000_012615.bin**) is now available for download and installation.

Vari-Lite suggests all owners and users of the VL4000 Spot Luminaires download and install this new version of software from the Support section of the Vari-Lite web site (www.vari-lite.com).

Please review this bulletin in its entirety before downloading and installing the software.

Note: VL4000 Spot Luminaires manufactured on and after **02/05/15** will have this software installed. This software may be loaded in all previously manufactured fixtures.



Important Notes About this Version of Software

- * *After installing this software update, some show programming may require modification. Certain fixture operation will be affected by installing this software.*
- * *Power recycling is required after new software is installed.*

About PEGASUS Upload Software

For instructions on downloading and installing VARI***LITE** luminaire software, refer to luminaire's user manual.

The PEGASUS Upload Software and luminaire firmware files are available for download, at no charge, from the Philips Vari-Lite web site at www.vari-lite.com in any luminaire product downloads support section.

For more information on PEGASUS Upload Software, please refer to Vari-Lite Technical Notice TN-349 (located in any product downloads Support section on the Vari-Lite web site) or contact your Authorized VARI***LITE** Dealer or Vari-Lite customer service.

If you have any questions regarding this release or your VARI***LITE** product, please contact Vari-Lite Customer Service at 1-877-VARILITE (or +1-214-647-7880) or via e-mail at entertainment.service@philips.com.

Release Notes

Updates to VL4000 Spot Luminaire Software (01/26/15):

- Incorporates features from VL4000 Spot Luminaire software 01/26/15. Refer to technical bulletin LSW-082 for pertinent information.
- This version of software temporarily removes normal (longest) path option for Gobo Wheels and always follows shortest path.
- Corrects a bug reported to set Studio/Standard Mode from the menu.
- Corrects a bug reported on menu to wake up from Shutdown.