

**PRODUCT:** VL3500™ Wash and VL3500™ Wash FX Luminaires

**SUBJECT:** Caution Against Direct Sunlight Through Front Lens Assembly

### OVERVIEW

---

Vari-Lite would like to remind all owners and users of VL3500™ Wash and VL3500™ Wash FX luminaires not to allow direct sunlight or light from neighboring fixtures directly through the front lens assembly. See "[Precautions](#)" for more information.

If you have any questions as to any aspect of this Technical Notice, please contact Vari-Lite customer service at 1-877-VARILITE or +1-214-647-7880.





---

**Note:** This technical notice is for information purposes only. Owners and users are not required to inspect or make any changes to their fixtures.

---



---

**WARNING:** Any repairs or maintenance to VARI\*LITE® luminaires should only be performed by a trained and qualified service technician or at an Authorized VARI\*LITE® Service facility.

---

### PRECAUTIONS



---

The design and nature of the VL3500™ Wash and VL3500™ Wash FX front lens assembly is to efficiently focus the light energy from the luminaire's lamp for maximum light output.

- When the front lens assembly is exposed to direct sunlight or intense light from neighboring fixtures, the lens will collect and intensify this light and focus it back into the fixture. Intense sunlight can cause damage to internal assemblies contained within the fixture.
- When fixture is not in use and direct sunlight or other intense light is present, position VL3500™ Wash or VL3500™ Wash FX luminaires so the front lens assembly is not directly exposed to the light source.

### CONTACT INFORMATION

---

For more information on this technical notice or on VARI\*LITE® products, please contact your Authorized VARI\*LITE® Dealer or Vari-Lite customer service.