

SUBJECT: VL3500™ Wash and Wash FX Luminaire Software Update	SERIES: 3000
DISTRIBUTION: Service Centers, End Users	STATUS: Routine

Introduction

Embedded Software Update

Software update **10/23/08** for **VL3500™ Wash/Wash FX Luminaires** is now available. This technical bulletin covers all changes in this new version.

For instructions on downloading and installing VARI***LITE**[®] luminaire software, refer to technical note TN-279.

If you have any questions regarding this release or your VARI***LITE**[®] product, please contact Vari-Lite Customer Service at 1-877-VARILITE (or +1-214-647-7880) or via e-mail at customerservice@genlytecontrols.com.

Release Notes

Improvements in the New Version

VL3500™ Wash and Wash FX Luminaires:

- This version fixes a pan-calibration problem.

VARI***LITE**[®], VL500™, VL1000™, VL2000™, VL2500™, VL3000™, and VL3500™ are trademarks of Philips Group.

24-NOVEMBER-2008

BULLETIN NO. **LSW-047**

Vari-Lite is a Philips group brand

PHILIPS