


SUBJECT: VL3500™ Wash Luminaire Software Update	SERIES: 3500
DISTRIBUTION: Service Centers, End Users	STATUS: Routine


## Introduction

---

### Embedded Software Update

Software update **08/02/07** for **VL3500™ Wash Luminaires** is now available. This technical bulletin covers all changes in this new version.

For instructions on downloading and installing VARI\*LITE® luminaire software, refer to technical bulletin LSW-002.

If you have any questions regarding this release or your VARI\*LITE® product, please contact Vari-Lite Customer Service at 1-877-VARILITE (or +1-214-647-7880) or via e-mail at [customerservice@genlytecontrols.com](mailto:customerservice@genlytecontrols.com).

## Release Notes

---

### Improvements in New Version

#### **VL3500™ Wash Luminaires:**

- On rare occasions, with software version 06/19/07 and earlier, pan response could be half the value entered for timing. Version 08/02/07 fixes this problem, and pan and tilt now respond normally to the focus timing channel.