

PRODUCT: VARI*LITE VL550 Wash Luminaires


SUBJECT: Connector Removal

OVERVIEW




Note: This technical notice is for information purposes only. Owners and users are not required to take any action of any kind in response to this notice.

Vari-Lite has made a design change in all versions of the VL550 Wash Luminaire. This design change involves the removal of a connector in the fixture's upper enclosure. Originally, this connector was added to the fixture to allow remote addressing of the fixture before it was put into service. This feature was never developed and the connector is unused. Vari-Lite has decided to remove this connector and add a cover plate to replace it as illustrated in [Figure 1](#).



*Old Style Upper Enclosure
(showing connector)*





*New Style Upper Enclosure
(showing cover plate)*

Figure 1: VL550 Wash Enclosure (Connector Removal)

- As this connector was never used, it is no longer available from Vari-Lite.
- This design change does not affect the fixture's performance or operation. This notice is for informational purposes only.
- All fixtures manufactured from 10/17/12 will no longer have this connector installed during manufacturing.

If you have any questions as to any aspect of this Technical Notice, please contact Vari-Lite customer service at 1-877-VARILITE or +1-214-647-7880.

CONTACT INFORMATION

For more information on this technical notice or on VARI*LITE products, please contact your Authorized VARI*LITE Dealer or Vari-Lite customer service.